

Field Report No.: 01														01	
SP&A Project No:			22.331					Report Date: 09-13-202						Time:	9:30AM
Project: Ledyard Board of Educ (Name & Location) 4 Blonders Boulevard Ledyard, CT 06339							ation								
			General												
		14/	The Imp	erial	Com	ipany,		0	4	_				- 6 \A/ 1-	
Weather □ Temp. Range: 75°						Site Site	Site Conditions					Day of Week			
	-	Range: <u>75°</u>	□ Foggy □ Warm				⊠ Clear □ Muddv			Windy	•			☐ Thurse ☑ Friday	,
			□ Foggy □ Cold				□ Muddy □ Other			windy				□ Saturd	
Type of Work Observed Being Performed														ay	
					Gener		13		Specialties/	Food	19		Sprinkle	ər	
	_	Trac			s/Drywall			Service				-			
2		Demolition		8			ws & Doors	14		Elevators		20		Finish n	
3		Concrete						15		Plumbing		21		Iron wo	
4				10	Floor		ng	16	<u> </u>	HVAC		22	<u> </u>		Tri-state)
5	Steel/Misc. Metals		11 12		Pool	ng/Interior	17	<u> </u>	Electrical		23 24	<u> </u>	Audio v Other:	/is/Low Volt	
6  Carpentry/Casework/ Mill Work			Ork/	12		Finish		18		Temperature Controls/BM		24		Other:	
Wo	rk Pe	erformed at time	of site vis	sit:											
	- Approximate number of workers on site – 0 - No workers on site														
General Remarks: - Installing of the metal roof on roof A still needs to take place.															
					still	needs	to take place.								
<ul> <li>Roof B has peel &amp; stick installed.</li> <li>Over flow pipe has been installed with new plywood covering old cavity for the overflow pipe.</li> </ul>															
- Roof hatch needs to be replaced with guards. See attached photo.															
- Roof membrane for vertical penetrations (i.e. hatch, roof top units etc.) has been installed.															
-	• · · · · · · · · · · · · · · · · · · ·														
Visitors:															
- None.															
Construction Administrator: <u>Steven</u>								(Signature)					9/26/2024 (Date)		
Cop	oies T	o: 🗆 CA 🛛	Architect		X	Contra	actor 🛛 🖾 Ow	ners							

PHOTOS (see following pages);



Field Report Page 2 of 4

#### Roof B - Northwest view



Roof B – New hatch needs to be replaced with guards





## Roof B – Roof drain & over flow pipe



Roof A – West elevation





Silver Petrucelli + Associates 3190 Whitney Avenue | Hamden CT 06518 311 State Street | New London CT 06320 203 230 9007 s*ilverpetrucelli.com* 

## Roof B – Missing third support for chimney pipe

# Field Report Page 4 of 4



#### Roof plan

