

Silver Petrucelli + Associates 3190 Whitney Avenue | Hamden CT 06518 311 State Street | New London CT 06320 203 230 9007 silverpetrucelli.com


Field Report
Page 1 of 6

| Field Report No.: 04 | | | | | | | | | | | | | | | |
|--|-----------------------------------|------------------------------|-----------------------------------|----------------|-------|------------------|--------------------|-------------------------|------------|-------------------------|---------------------|----|---------------------|--------------------|--|
| SP&A Project No: 22.3 | | | | | | | | Report Date: 08-02-2024 | | | | | | Time: 9:30AM | |
| | (| Project: Name & Location) | Juliet Lo 1854 CT- Gales Fe | -12 erry, (| CT 0 | 6335 | | | | | | | | | |
| General Contractor: Gold Seal Roofing, LLC | | | | | | | | | | | | | | | |
| Weather | | | | | | | Site Conditions | | | | | | Day of Week | | |
| ☐ Temp. Range: 79° | | | | | | | ⊠ Clear | | | Dusty | ☐ Monday ☐ Thursday | | | ☐ Thursday | |
| ⊠ Clear □ Rain □ Foggy | | | | ☐ Warm | | | ☐ Muddy | | | ☐ Windy ☐ Tues | | | day ⊠ Friday | | |
| □ Overcast □ Snow □ Cold | | | | | Hot | | ☐ Other | □ Wed | | | nesday 🗆 Saturday | | | | |
| Type of Work Observed Being Performed | | | | | | | | | | | | | | | |
| 1 | | Site work | Site work | | | Gene | ral s/Drywall | 13 | | Specialties/ Service | Food | 19 | | Sprinkler | |
| 2 | | Demolition | molition | | | Wind | ows & Doors | 14 | | Elevators | | 20 | \boxtimes | Finish metal | |
| 3 | | Concrete | 9 | × | Roofi | ng | 15 | | Plumbing | | 21 | | Iron workers | | |
| 4 | | <u> </u> | | | | Floori | ing | 16 | | HVAC | | 22 | | Tester (Tri-state) | |
| 5 | | Steel/Misc. Metals | 11 | | Pool | | 17 | | Electrical | | 23 | | Audio Vis/Low Volt | | |
| 6 | 6 ☐ Carpentry/Casework/ Mill Work | | | 12 | | Painti Finish | ng/Interior nes | 18 | | Temperature Controls/BM | | 24 | | Other: | |
| | | erformed at time | | - | | | | | | | | | | | |
| Approximate number of workers on site – 10 Working on installing insulation boards on roof B. Working on installing the metal trim above the windows Working on general site clean Installation of the electrical line work is in progress. See attached photo. | | | | | | | | | | | | | | | |
| General Remarks: | | | | | | | | | | | | | | | |
| Project is on schedule. Half of roof B insulation panels are installed at the time of the site visit. The second half will be installed the tomorrow (8/3) as well as the base cap for water issues over the weekend. The roof drain line has been corrected. The original line was not connected to any pipes and had ended below ground into the soil. See attached photo. | | | | | | | | | | | | | | | |
| Vis | Visitors: | | | | | | | | | | | | | | |
| - None. | | | | | | | | | | | | | | | |
| Construction Administrator: Steven (Print No. | | | | | | | | | (Sigr | nature) | | | 8/05/2024 (Date) | | |
| Co | ies T | o: 🗆 CA 🗆 | Architect | | × | Contr | actor ⊠ Ow | ners | | | | | | | |


PHOTOS (see next page);





















Electrical trench work in progress



Roof drainage line corrected and needs to be backfilled



Field Report Page 6 of 6

Roof plan

