

Field Report No.: 11															
	SP	&A Project No:	22.331							Report Date	4	Time: 9:30AM			
	(Project: Name & Location)	Juliet Lo 1854 CT- Gales Fe General	12 rry, (СТ 0	6335									
			Gold Sea	al Ro	ofin	g, LLC							_		
Weather							Site Conditions					Day of Week			
		Range: 70°					⊠ Clear			Dusty	□ Monday □ Thursday				
☐ Clear ☐ Rain ☐ Fog ⊠ Overcast ☐ Snow ☐ Co							☐ Muddy □ Other		L	Windy	5			⊠ Friday	
☑ Overcast □ Snow □ Cold □ Hot □ Other Type of Work Observed Being										🛛 🗆 Wednesday 🛛 Saturday					
4		Cite weath	1					a Bein 13			Feed	19		Onvinkler	
1		Site work 7				General Trades/Drywall		13		Specialties/ Food Service		19		Sprinkler	
2		Demolition	8			ows & Doors	14		Elevators		20	\boxtimes	Finish metal		
3		Concrete				Roofi	ng	15		Plumbing		21		Iron workers	
4		Masonry	10		Floor	ing	16		HVAC		22		Tester (Tri-state)		
5		Steel/Misc. Metal	11		Pool		17		Electrical		23		Audio Vis/Low Volt		
6	6 Carpentry/Casework/ Mill Work			12		Paint Finis	ing/Interior hes	18		Temperature Controls/BN		24		Other:	
Wo	Work Performed at time of site visit:														
- Approximate number of workers on site – 2 - Metal installers were on site working on miscellaneous items															
Ge	neral	Remarks:													
 Students are now back in school. Miscellaneous metal work needs to be completed. Miscellaneous items are left. Reviewed a few items that need attention. See attached photos. 															
Visitors:															
- None.															
c	onstr	ruction Administrat	tor:		S	Steven (Print I	June Jame)	(Signature)						9/26/2024 (Date)	
Cop	oies T	o: 🗆 CA 🗌	Architect		X	Conti	ractor 🛛 🖾 Ow	/ners							

PHOTOS;



Field Report Page 2 of 5

Roof A - Looking northwest



Roof A – PVC needs to be fixed as well as adding downspout adapter (west wall of roof A)



Silver Petrucelli & Associates, Inc. ©

FIELD REPORT



Silver Petrucelli + Associates 3190 Whitney Avenue | Hamden CT 06518 311 State Street | New London CT 06320 203 230 9007 silverpetrucelli.com

Roof A – Looking east




Roof A - Nail heads need to be covered with covered sheet







Roof A - Rivets for downspouts - Mandrel head (pin) needs to be flush with the primary head (ring)





Silver Petrucelli + Associates 3190 Whitney Avenue | Hamden CT 06518 311 State Street | New London CT 06320 203 230 9007 silverpetrucelli.com

