

Page 1	of 4
--------	------

Field Report											ort No.:	09				
SP&A Project No: 22.331									Report Date	e: 10-0	4-202	4	Time:	9:30AM		
	(Project: Name & Location)	Gales Fe 1854 CT Gales Fe	-12												
	General Contractor:															
The Imperial Company, Inc. Weather Day of Week																
			iner				Site Site							ay of Week		
	emp. Clear	Range: <u>57°</u> □ Rain	Foggy		Wa	-	⊠ Clear □ Muddv	□ Dusty □ Mond □ Windy □ Tueso					, ,			
			□ Foggy □ Cold		Ho		☐ Muddy □ Other			windy	uay 1esdav	⊠ Friday v □ Saturday				
□ Overcast □ Snow □ Cold □ Hot □ Other □ Wednesday □ Saturday Type of Work Observed Being Performed																
1		Site work		7		Gene		13		Specialties/	Food	19		Sprinkle	er	
							s/Drywall			Service				-		
2		Demolition					ows & Doors	14		Elevators		20	X	Finish metal		
3		Concrete		9		Roofi	0	15		Plumbing		21		Iron workers		
4		Masonry	10 🛛 Floori			ing	16		HVAC		22		Tester (Tri-state)			
5		Steel/Misc. Metal		11 🛛 Pool				17		Electrical		23		Audio Vis/Low Volt		
6	6 □ Carpentry/Casework/ 12 Mill Work			12		Paint Finisl	18		Temperature Controls/BN	24		Other:				
Work Performed at time of site visit:																
 Approximate number of workers on site – 2 Installing trim for the overhangs on the walkway overhang. See attached photo. 																
										ork as per the	installer	as pe	r the	Forman		
 the day of the visit the installers should be installing about 500 lineal feet of trim work as per the installer as per the Forman. Back area metal panels has been completed on one side for the arched area roof (roof E) and the diagonal extension rood (roof F). 																
General Remarks:																
 Installation of the metal roof panels needs to continue. The dividers between the sections of roof panels need the divider install. See attached photo. 																
Visitors:																
- None.																
Construction Administrator: <u>Steven June</u> <u>10/7/2024</u> (Print Name) (Signature) (Date)									10/7/2024 (Date)							
Copies To: CA Architect Contractor Owners																

PHOTOS (see attached photos);



Field Report Page 2 of 4

Roof E – Metal divider needs to be installed at the ridge line (underlayment is exposed)



Roof E – Metal panels installed





Silver Petrucelli + Associates 3190 Whitney Avenue | Hamden CT 06518 311 State Street | New London CT 06320 203 230 9007 s*ilverpetrucelli.com*

Field Report Page 3 of 4

Roof E – Metal panels installed



Roof F – Metal roof installed





Silver Petrucelli + Associates 3190 Whitney Avenue | Hamden CT 06518 311 State Street | New London CT 06320 203 230 9007 s*ilverpetrucelli.com*

Roof E – Base area closest to the school



Roof plan

