

## Silver Petrucelli + Associates 3190 Whitney Avenue | Hamden CT 06518 311 State Street | New London CT 06320 203 230 9007 silverpetrucelli.com

**Field** Report
Page 1 of 5

									ļ	ield	Repo	ort No.:	03	
SP&A Project No: 22.331		22.331	331						Report Date: 07-26-2			4	Time:	9:30AM
	Project: (Name & Location)	Juliet Lo 1854 CT- Gales Fe General Gold Sea	·12 ·rry, Cont	CT 0	6335 or:	;								
Weather					Site	Site Conditions						Day of Week		
☐ Temp. Range: 81°						☐ Clear			Dusty	☐ Monday ☐ Thurse			lay	
⊠ Clear □ Rain □ Foggy			☐ Warm			☐ Muddy		, ,			□ Tuesday ☑ Friday			
☐ Overcast ☐ Snow ☐ Cold				Hot	1	☐ Other				☐ Wednesday ☐ Saturda				ay
Type of Work Observed Being Performed														
1 🗆	Site work	Site work		7 ☐ Gene Trade		s/Drywall	13		Specialties/ Service	Food	19		Sprinkle	er e
2 🗆	Demolition		8			ows & Doors	14		Elevators		20	×	Finish n	netal
3 □			9	□ Roofi			15		Plumbing		21		Iron wo	rkers
4 🗆			10			ing	16		HVAC		22			Tri-state)
	5		11	□ Pool			17		Electrical	2				is/Low Volt
6 🗆	6 ☐ Carpentry/Casework/ Mill Work		12		Paint Finisl	ing/Interior nes	18		Temperature Controls/BN				Other:	
Work P	erformed at time	of site vis	it:											
- Approximate number of workers on site – 8 (7 roofers, 1 metal) - Working on installing the metal edging above the windows on roof A														
- Installing the lower blocking for the metal wall panels on roof B. See attached photo.														
Genera	I Remarks:													
	t is on schedule.													
	ctor is waiting on the						fB.							
	A, C, D, & E have th						ttaabaa	l nho	too					
	<ul> <li>Skylight opens have the plastic glass removed and are covered. See attached photos.</li> <li>Insulation panels are on the roof A waiting to be installed on roof B.</li> </ul>													
Visitors	Visitors:													
- None.														
Construction Administrator: Stever							(Sia	nature)				7/31/2024 (Date)		
Copies	Copies To: ☐ CA ☐ Architect ☒ Cont						wners		(Olgi					(Date)

PHOTOS (see next page)














Roof A - Base sheets down, need cap sheets











Page 5 of 5



ARCHITECTS ENGINEERS INTERIORS



