

## Silver Petrucelli + Associates 3190 Whitney Avenue | Hamden CT 06518 311 State Street | New London CT 06320 203 230 9007 silverpetrucelli.com

**Field** Report Page 1 of 4

Field Report No.:													13		
SP&A Project No: 22.331			22.331	2.331				Report Date: 11-15-2024 Tim						9:30AM	
(Name & Location) 1854				Gales Ferry School 854 CT-12 Gales Ferry, CT 06335											
			General C			or: pany, Inc.									
		Weat		IIai	COIIII		Site Conditions Day of Week								
☐ Temp. Range: 63°						⊠ Clear	Jona		Dusty	☐ Mond					
• • —			☐ Foggy		Warr	m □ Muddy			Windy	☐ Tues	•				
☐ Overcast ☐ Snow ☐ Cold				Hot	☐ Other				□ Wedr	□ Wednesday □ Saturday					
Type of Work Observed Being Performed															
1		Site work			_	General Trades/Drywall	13		Specialties/ Service	19		Sprinkler			
2		Demolition		8		Windows & Doors	14		Elevators	levators		X	Finish me	etal	
3		Concrete		9		Roofing	15		Plumbing		21		Iron work		
4	☐ Masonry			10   Flooring			16		HVAC	22		Tester (Tri-state)			
5 Steel/Misc. Metals			11		Pool	17 18		Electrical	23		Audio Vis	/Low Volt			
6			/OFK/	12		Painting/Interior Finishes	18	☐ Temperature Controls/BM			24		Otner:		
Wo	rk Pe	erformed at time	of site visi	it:	<u> </u>										
- Approximate number of workers on site – 5 - Installing the panels on the north side of roof A, to the left of the main entrance. See attached photos.															
General Remarks:															
<ul> <li>Crew will be working on Saturday (11/16).</li> <li>Work is to continue working east on the north roof A.</li> <li>IM is using red screws for easier identification for penetration thru the decking.</li> <li>As per the site meeting on Monday (11/11), Imperial is to remove the newly installed panels on the gym &amp; the wing of roof A (in selected</li> </ul>															
areas).  - Areas where the screws were removed and not placed back in the same hole, holes are being caulked.  - Roofer as now using 8" screws, except at the drip edges since there is blocking for the screws to grab.  - Installers have completed the valleys.															
- La	<ul> <li>For panels that meeting with the structure or valleys, (no full panels) have not been installed.</li> <li>Large panels are temporarily placed in place. Imperial has confirmed that they are secured.</li> <li>Screws depths were discussed and confirmed that the screws are penetrating the decking with the required under deck exposure.</li> </ul>														
Vis	Visitors:														
- None.															
						teven June (Print Name)							11/18/2024 (Date)		
Copies To: ☐ CA ☐ Architect ☐ Contractor ☐ Owners															

PHOTOS (see attached photos);

Field Report Page 2 of 4

Roof A – North elevation looking southeast







Field Report Page 3 of 4

Roof A - Panels to be fastened in other areas



Roof A - Overview of the west elevation



ARCHITECTS ENGINEERS INTERIORS





