

Silver Petrucelli + Associates 3190 Whitney Avenue | Hamden CT 06518 311 State Street | New London CT 06320 203 230 9007 silverpetrucelli.com

Field Report Page 1 of 4

Field Report No.: 13													ort No.: 13		
SP&A Project No: _22.331										Report Date	e: <u>11-</u> 1	5-202	4	Time: 9:30AM	
	(Project: Name & Location)	Gales Fe 1854 CT- Gales Fe	12											
	General Contractor: The Imperial Company, Inc.														
		Woat		eriai	Com	npany,	Inc. Site Conditions Day of Week								
Weather ☐ Temp. Range: 63°							⊠ Clear					☐ Monday ☐ Thursday			
⊠ Clear □ Rain □ Foggy				□ Warm			☐ Muddy	□ Windy			☐ Tuesday ☐ Friday			-	
□ Overcast □ Snow □ Cold				☐ Hot			□ Other				☐ Wednesday ☐ Saturday			•	
Type of Work Observed Being Performed															
1		Site work	7		Gener Trade:	al s/Drywall	13		Specialties/ Service	19		Sprinkler			
2		Demolition	molition				ws & Doors	14		Elevators		20	X	Finish metal	
3		Concrete			□ Roofi □ Floor		•	15		Plumbing	bing			Iron workers	
4]	Masonry				Floori	ng	16		HVAC		22	<u> </u>	Tester (Tri-state)	
6	5 ☐ Steel/Misc. Metals 6 ☐ Carpentry/Casework/			11		Pool	ng/Interior	17 18		Electrical Temperature		23 24		Audio Vis/Low Volt Other:	
Mill Work				12		Finish		10	Ш	Controls/BM		24	ш	Other.	
Wo	rk Pe	erformed at time	of site vis	it:						<u> </u>					
- Approximate number of workers on site – 5 - Installing the panels on the north side of roof A, to the left of the main entrance. See attached photos.															
General Remarks:															
		ill be working on S													
- Work is to continue working east on the north roof A IM is using red screws for easier identification for penetration thru the decking.															
- As per the site meeting on Monday (11/11), Imperial is to remove the newly installed panels on the gym & the wing of roof A (in selected															
areas).															
- Areas where the screws were removed and not placed back in the same hole, holes are being caulked Roofer as now using 8" screws, except at the drip edges since there is blocking for the screws to grab.															
- Installers have completed the valleys.															
- For panels that meeting with the structure or valleys, (no full panels) have not been installed.															
 Large panels are temporarily placed in place. Imperial has confirmed that they are secured. Screws depths were discussed and confirmed that the screws are penetrating the decking with the required under deck exposure. 															
- Screws deputs were discussed and committee that the screws are penetrating the decking with the required under deck exposure.															
Visitors:															
- None.															
Construction Administrator: Steven							June							11/18/2024	
						(Print N				(Sign	nature)			(Date)	
Cop	ies T	o: 🗆 CA 🗆	Architect		X	Contra	actor 🗵 Ow	ners							

PHOTOS (see attached photos);

Field Report Page 2 of 4

Roof A – North elevation looking southeast







Field Report Page 3 of 4

Roof A - Panels to be fastened in other areas



Roof A - Overview of the west elevation



ARCHITECTS ENGINEERS INTERIORS





