
Route 12 Cross Culvert (west side) Above Pine Swamp Brook Pond

Before



After



Route 12 Cross Culvert (east side)

After



Christy Hill Road Culvert Discharges Above Route 12 Cross Culvert

After (you can see the waterline from the before condition)

