



<b>Field Report No.:</b>		<b>22</b>	
<b>SP&amp;A Project No:</b> 22.331		<b>Report Date:</b> 2.07.2025	<b>Time:</b> 9:30AM
<b>Project:</b> Gales Ferry School (Name & Location) 1854 CT-12 Gales Ferry, CT 06335  <b>General Contractor:</b> The Imperial Company, Inc.			
<b>Weather</b>		<b>Site Conditions</b>	
<input type="checkbox"/> Temp. Range: 34° <input type="checkbox"/> Clear <input type="checkbox"/> Rain <input type="checkbox"/> Foggy <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Overcast <input type="checkbox"/> Snow <input type="checkbox"/> Cold <input type="checkbox"/> Hot		<input checked="" type="checkbox"/> Clear <input type="checkbox"/> Dusty <input type="checkbox"/> Muddy <input type="checkbox"/> Windy <input type="checkbox"/> Other	
<b>Day of Week</b>			
<input type="checkbox"/> Monday <input type="checkbox"/> Thursday <input checked="" type="checkbox"/> Tuesday <input type="checkbox"/> Friday <input type="checkbox"/> Wednesday <input type="checkbox"/> Saturday			
<b>Type of Work Observed Being Performed</b>			
1	<input type="checkbox"/> Site work	7	<input type="checkbox"/> General Trades/Drywall
2	<input type="checkbox"/> Demolition	8	<input type="checkbox"/> Windows & Doors
3	<input type="checkbox"/> Concrete	9	<input type="checkbox"/> Roofing
4	<input type="checkbox"/> Masonry	10	<input type="checkbox"/> Flooring
5	<input type="checkbox"/> Steel/Misc. Metals	11	<input type="checkbox"/> Pool
6	<input type="checkbox"/> Carpentry/Casework/ Mill Work	12	<input type="checkbox"/> Painting/Interior Finishes
13	<input type="checkbox"/> Specialties/ Food Service	14	<input type="checkbox"/> Elevators
15	<input type="checkbox"/> Plumbing	16	<input type="checkbox"/> HVAC
17	<input type="checkbox"/> Electrical	18	<input type="checkbox"/> Temperature Controls/BMS
19	<input type="checkbox"/> Sprinkler	20	<input checked="" type="checkbox"/> Finish metal
21	<input type="checkbox"/> Iron workers	22	<input type="checkbox"/> Tester (Tri-state)
23	<input type="checkbox"/> Audio Vis/Low Volt	24	<input type="checkbox"/> Other:
<b>Work Performed at time of site visit:</b>			
- Approximate number of workers on site – 4 - Continuation of snow guards was in progress - Ridge vent work was in progress. - Fastening the panels to the valley metal on Roof E was in progress. See attached photo.			
<b>General Remarks:</b>			
- Box out of the mechanical exhaust was completed as per Garland's direction. See attached photo.			
<b>Visitors:</b>			
- None.			
<b>Construction Administrator:</b> Steven June		<b>1/28/25</b>	
<i>(Print Name)</i>		<i>(Signature)</i>	
		<i>(Date)</i>	
<b>Copies To:</b>	<input type="checkbox"/> CA	<input type="checkbox"/> Architect	<input checked="" type="checkbox"/> Contractor <input checked="" type="checkbox"/> Owners

Areas of observation (see attached pages) –

Roof D – Ridge work in progress



Roof E – Securing panels to valley





**Roof F – Installing snow guards**



**Roof E – Box out of roof exhaust**



**Roof plan**

