



Field Report No.:		11	
SP&A Project No: <u>22.331</u>		Report Date: <u>09-20-2024</u>	Time: <u>9:30AM</u>
Project: <u>Juliet Long School</u> (Name & Location) <u>1854 CT-12</u> <u>Gales Ferry, CT 06335</u>			
General Contractor: <u>Gold Seal Roofing, LLC</u>			
Weather		Site Conditions	
<input type="checkbox"/> Temp. Range: <u>70°</u> <input type="checkbox"/> Clear <input type="checkbox"/> Rain <input type="checkbox"/> Foggy <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Overcast <input type="checkbox"/> Snow <input type="checkbox"/> Cold <input type="checkbox"/> Hot		<input checked="" type="checkbox"/> Clear <input type="checkbox"/> Dusty <input type="checkbox"/> Muddy <input type="checkbox"/> Windy <input type="checkbox"/> Other	
Day of Week			
<input type="checkbox"/> Monday <input type="checkbox"/> Thursday <input type="checkbox"/> Tuesday <input checked="" type="checkbox"/> Friday <input type="checkbox"/> Wednesday <input type="checkbox"/> Saturday			
Type of Work Observed Being Performed			
1	<input type="checkbox"/> Site work	7	<input type="checkbox"/> General Trades/Drywall
2	<input type="checkbox"/> Demolition	8	<input type="checkbox"/> Windows & Doors
3	<input type="checkbox"/> Concrete	9	<input type="checkbox"/> Roofing
4	<input type="checkbox"/> Masonry	10	<input type="checkbox"/> Flooring
5	<input type="checkbox"/> Steel/Misc. Metals	11	<input type="checkbox"/> Pool
6	<input type="checkbox"/> Carpentry/Casework/ Mill Work	12	<input type="checkbox"/> Painting/Interior Finishes
13	<input type="checkbox"/> Specialties/ Food Service	14	<input type="checkbox"/> Elevators
15	<input type="checkbox"/> Plumbing	16	<input type="checkbox"/> HVAC
17	<input type="checkbox"/> Electrical	18	<input type="checkbox"/> Temperature Controls/BMS
19	<input type="checkbox"/> Sprinkler	20	<input checked="" type="checkbox"/> Finish metal
		21	<input type="checkbox"/> Iron workers
		22	<input type="checkbox"/> Tester (Tri-state)
		23	<input type="checkbox"/> Audio Vis/Low Volt
		24	<input type="checkbox"/> Other:
Work Performed at time of site visit:			
- Approximate number of workers on site – 2 - Metal installers were on site working on miscellaneous items			
General Remarks:			
- Students are now back in school. - Miscellaneous metal work needs to be completed. - Miscellaneous items are left. - Reviewed a few items that need attention. See attached photos.			
Visitors:			
- None.			
Construction Administrator:		<u>Steven June</u>	<u>9/26/2024</u>
		<small>(Print Name)</small>	<small>(Signature)</small>
Copies To:	<input type="checkbox"/> CA	<input type="checkbox"/> Architect	<input checked="" type="checkbox"/> Contractor <input checked="" type="checkbox"/> Owners

PHOTOS;

Roof A – Looking northwest



Roof A – PVC needs to be fixed as well as adding downspout adapter (west wall of roof A)




Roof A – Looking east



Roof A – Nail heads need to be covered with covered sheet



Roof A – Top of green metal trim needs to be caulked



Roof A – Rivets for downspouts – Mandrel head (pin) needs to be flush with the primary head (ring)



Roof plan

