



<b>Field Report No.:</b>		<b>01</b>					
<b>SP&amp;A Project No:</b> 22.331		<b>Report Date:</b> 09-13-2024	<b>Time:</b> 9:30AM				
<b>Project:</b> Ledyard Board of Education (Name & Location) 4 Blonders Boulevard Ledyard, CT 06339  <b>General Contractor:</b> The Imperial Company, LLC							
Weather		Site Conditions		Day of Week			
<input type="checkbox"/> Temp. Range: 75° <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Rain <input type="checkbox"/> Foggy <input type="checkbox"/> Warm <input type="checkbox"/> Overcast <input type="checkbox"/> Snow <input type="checkbox"/> Cold <input type="checkbox"/> Hot		<input checked="" type="checkbox"/> Clear <input type="checkbox"/> Dusty <input type="checkbox"/> Muddy <input type="checkbox"/> Windy <input type="checkbox"/> Other		<input type="checkbox"/> Monday <input type="checkbox"/> Thursday <input type="checkbox"/> Tuesday <input checked="" type="checkbox"/> Friday <input type="checkbox"/> Wednesday <input type="checkbox"/> Saturday			
Type of Work Observed Being Performed							
1	<input type="checkbox"/> Site work	7	<input type="checkbox"/> General Trades/Drywall	13	<input type="checkbox"/> Specialties/ Food Service	19	<input type="checkbox"/> Sprinkler
2	<input type="checkbox"/> Demolition	8	<input type="checkbox"/> Windows & Doors	14	<input type="checkbox"/> Elevators	20	<input type="checkbox"/> Finish metal
3	<input type="checkbox"/> Concrete	9	<input type="checkbox"/> Roofing	15	<input type="checkbox"/> Plumbing	21	<input type="checkbox"/> Iron workers
4	<input type="checkbox"/> Masonry	10	<input type="checkbox"/> Flooring	16	<input type="checkbox"/> HVAC	22	<input type="checkbox"/> Tester (Tri-state)
5	<input type="checkbox"/> Steel/Misc. Metals	11	<input type="checkbox"/> Pool	17	<input type="checkbox"/> Electrical	23	<input type="checkbox"/> Audio Vis/Low Volt
6	<input type="checkbox"/> Carpentry/Casework/ Mill Work	12	<input type="checkbox"/> Painting/Interior Finishes	18	<input type="checkbox"/> Temperature Controls/BMS	24	<input type="checkbox"/> Other:
Work Performed at time of site visit:							
- Approximate number of workers on site – 0 - No workers on site							
General Remarks:							
- Installing of the metal roof on roof A still needs to take place. - Roof B has peel & stick installed. - Over flow pipe has been installed with new plywood covering old cavity for the overflow pipe. - Roof hatch needs to be replaced with guards. See attached photo. - Roof membrane for vertical penetrations (i.e. hatch, roof top units etc.) has been installed. -							
Visitors:							
- None.							
<b>Construction Administrator:</b> Steven June						<b>9/26/2024</b>	
<small>(Print Name)</small>						<small>(Signature)</small>	
<small>(Date)</small>						<small>(Date)</small>	
<b>Copies To:</b>		<input type="checkbox"/> CA <input type="checkbox"/> Architect <input checked="" type="checkbox"/> Contractor <input checked="" type="checkbox"/> Owners					

PHOTOS (see following pages);

**Roof B – Northwest view**



**Roof B – New hatch needs to be replaced with guards**





**Roof B – Roof drain & over flow pipe**



**Roof A – West elevation**





**Roof B – Missing third support for chimney pipe**



**Roof plan**

